
Flexion Extruder Mount
for JGAurora Z 605S
Andrew L. Sandoval
8-32 tap
Motor Support bolt holes
TEXT FACES BOTTOM of SQUARE TUBE
Bottom


Text faces outward
Back/Mount Side
This face mounts to x-carriage


Screw Driver Access Holes
Fan Mount
3mm tapped holes
Front Face
Text faces outward