


Poor Man's 3D Printer



Note:
 Stepper X/Y/Z
 needs 5V
 Extruder Stepper
 needs 12V

R1: Extruder
 R2: Heat Bed

Thermistors
 Heat Bed / Extruder