






A = PWM
C = 0-30Vdc
D = 24Vdc
F+I = 5Vdc
G+J = 3,3Vdc
L = 12Vdc
B+E+H+K = TESTVELD



A
B
C
D
E
F
G
H



A

B

C


D

E

F

G

H



HMI2

