

Al iniciar el monitor y al tocar el logo

		eje "X" columna															
		0	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
eje "Y" Fila	0		M	o	n	i	t	o	r		c	a	l	i	d	a	d
	1					d	e		a	i	r	e					

Al presionar "A"

		eje "X" columna															
		0	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
eje "Y" Fila	0			T	e	m	p	.				H	u	m	.		
	1			2	5	°	C					2	0	%			

Al presionar "B"

		eje "X" columna															
		0	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
eje "Y" Fila	0	D	i	ó	x	i	d	o		c	a	r	b	o	n	o	
	1				4	0	5	p	p	m		C	o	2			

Al presionar "A+B"

		eje "X" columna															
		0	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
eje "Y" Fila	0	C	o	n	c	.	p	a	r	t	.		u	g	/	m	3
	1	P	M	2	.	5		7			P	M	1	0		1	5

 Datos fijos

 Datos del sensor